


# saas shepherd

INSTRUCTIONS





Shepherd light fixture with casting adapter




Mounting ring




Electrical pipe

LED 6W	Ra 90	3 SDCM	500 lumen	500 mA	IP65
DIM	DMX	DALI	 -20°C...+50°C		CE


1




2



3




4





Mounting ring and pipe edge are casted in on exact same level.  
Hat nut and nuts stay on the screw while casting to prevent the thread from getting stuck by concrete.

**IMPORTANT:** Pay attention to bolt hole direction and light fixture direction. They need to be aligned.


**Cast the Electrical Pipe as straight as possible.** Only small angle adjustments are possible later!







After connecting the cables the light fixture is pushed into the pipe and secured with the hat nuts.



Raise the nuts under the disc to fine adjust the angle of the light fixture. Then tighten up the hat nuts on top of the washers.

