


## saas power beam concrete instructions









1




2








4




Mounting ring and pipe edge are casted in on exact same level. Hat nut and nuts stay on the screw while casting to prevent the thread from getting stuck by concrete.

Cast the Electrical Pipe as straight as possible. Only small angle adjustments are possible later!









After connecting the cables the light fixture is pushed into the pipe and secured with the hat nuts.



